ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalakunte
Street ID	**Street Name**	**Significant Landmark**
W0566, W0675, W0570, W0548, W0487, W0677, W0679, W	NA, 16th Crs, 1st Crs	NEAR KEB OFFICE
Segment No.	**Total Length (m)**	
14/C-W0566/S084344	792.15	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	140.99	77.498420	13.052745	77.498722	13.053984	W0548	W0572
2	137.44	77.498140	13.052839	77.498461	13.054041	W0675	W0572
3	74.49	77.497718	13.052501	77.498353	13.052243	W0572	W0548
4	210.30	77.497561	13.052150	77.498123	13.053967	W0548	W0566
5	228.93	77.499005	13.053922	77.498274	13.052003	W0548	W0566

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
IMPROVEMENTS TO ROADS AND DRAIN NEAR BEHIND WIDIA FACTORY TO SRIRAM REDDY HOUSEUPTO SWD	5000000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	DRAIN WORK	14-15-000046
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/246/2014-2015	09/02/2015	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		4999740.00
Phone No.	**E-Mail ID**	
8197839023		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		manjunath
Date of Inspection	**Remarks**	
02/03/2016		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range
Road Condition		This photo seems out of range

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು 3/3/2016 3:11 P
ಪೀಣ್ಯ ವಿಭಾಗ
ಪೂರ್ವ ವಲಯ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು